



Escuela Técnica Superior de Ingenieros de
Caminos, Canales y Puertos



**UNIVERSITAT
POLITÈCNICA
DE VALÈNCIA**

Design project of the structure of a residential building in the city of Castellón street Paseo Ribalta nº1

DOCUMENT Nº2 PLANS

Autor: Monika Przygocka

**Tutor: Ignacio Javier Payá Zaforteza
Janusz Dębiński**

Trabajo Fin de Master Junio 2019

Plans Index

- 1.1 Situation Plan
- 2.1 Underground garage - Architecture plan
- 2.2 Ground Floor - Architecture plan
- 2.3 First Floor - Architecture plan
- 2.4 Second Floor - Architecture plan
- 2.5 Third Floor - Architecture plan
- 2.6 Fourth Floor - Architecture plan
- 2.7 Utility Roof and Roof of staircase - Architecture plan
- 2.8 Section A-A'
- 2.9 Section B-B'
- 2.10 North-western facade
- 2.11 North-eastern facade
- 2.12 South-eastern facade
- 3.1 Ground Floor - Dead load walls
- 3.2 Ground Floor - Live Load Case 1
- 3.3 Ground Floor - Live Load Case 2
- 3.4 First Floor - Dead load walls
- 3.5 First Floor - Live Load Case 1
- 3.6 Ground Floor - Live Load Case 2
- 3.7 Second and Third Floor - Dead load walls
- 3.8 Second and Third Floor - Live Load Case 1
- 3.9 Second and Third Floor - Live Load Case 2
- 3.10 Fourth Floor - Dead load walls
- 3.11 Fourth Floor - Live Load Case 1
- 3.12 Fourth Floor - Live Load Case 2
- 3.13 Utility Roof - Dead load of floor and walls
- 3.14 Utility Roof - Live Load Case 1
- 3.15 Utility Roof - Live Load Case 2
- 4.1 Foundation - Longitudinal bottom reinforcement
- 4.2 Foundation - Transverse bottom reinforcement
- 4.3 Foundation - Longitudinal top reinforcement
- 4.4 Foundation - Transverse top reinforcement
- 4.5 Foundation - Frames 1
- 4.6 Foundation - Frames 2
- 4.7 Foundation - Frames 3
- 4.8 Foundation - Frames 4
- 5.1 Cross section of columns part 1
- 5.2 Cross section of columns part 2
- 5.3 Cross section of columns part 3
- 6.1 Ground Floor - Longitudinal bottom reinforcement
- 6.2 Ground Floor - Transverse bottom reinforcement
- 6.3 Ground Floor - Longitudinal top reinforcement
- 6.4 Ground Floor - Transverse top reinforcement

- 6.5 First Floor - Longitudinal bottom reinforcement
- 6.6 First Floor - Transverse bottom reinforcement
- 6.7 First Floor - Longitudinal top reinforcement
- 6.8 First Floor - Transverse top reinforcement
- 6.9 Second and Third Floor - Longitudinal bottom reinforcement
- 6.10 Second and Third Floor - Longitudinal bottom reinforcement
- 6.11 Second and Third Floor - Longitudinal top reinforcement
- 6.12 Second and Third Floor - Transverse top reinforcement
- 6.13 Fourth Floor - Longitudinal bottom reinforcement
- 6.14 Fourth Floor - Transverse bottom reinforcement
- 6.15 Fourth Floor - Longitudinal top reinforcement
- 6.16 Fourth Floor - Transverse top reinforcement
- 6.17 Utility Roof and Roof of staircase - Longitudinal bottom reinforcement
- 6.18 Utility Roof and Roof of staircase - Transverse bottom reinforcement
- 6.19 Utility Roof and Roof of staircase - Longitudinal top reinforcement
- 6.20 Utility Roof and Roof of staircase - Transverse top reinforcement
- 6.21 Ground Floor- Punching shear reinforcement
- 6.22 First Floor- Punching shear reinforcement
- 6.23 Second Floor- Punching shear reinforcement
- 6.24 Third Floor- Punching shear reinforcement
- 6.25 Fourth Floor- Punching shear reinforcement
- 6.26 Ground Floor - Frames Part 1
- 6.27 Ground Floor - Frames Part 2
- 6.28 Ground Floor - Frames Part 3
- 6.29 Ground Floor - Frames Part 4
- 6.30 Floor 1,2,3,4 - Frames Part 1
- 6.31 Floor 1,2,3,4 - Frames Part 2
- 6.32 Floor 1,2,3,4 - Frames Part 3
- 6.33 Utility Roof - Frames Part 1
- 6.34 Utility Roof - Frames Part 2
- 6.35 Utility Roof - Frames Part 3
- 6.36 Utility Roof- Frames Part 4
- 7.1 Stairs garage
- 7.2 Stairs from Ground Floor to First Floor
- 7.3 Stairs from First Floor to Utility Roof
- 8.1 Construction detail of base of column on mat foundation
- 8.2 Construction detail of base of column and wall on mat foundation
- 8.3 Construction detail of the beam and slab connection
- 8.4 Construction detail of column reinforcement