





LEGEND			
	Painted brick facing		Deteriorated concrete construction elements
	Facade without finished of fibre corrugated plates		Humidity
	Fibre corrugated plates with dirt and color fading		Currently façade rehabilitation




LEGEND	
	Facade without finished of fibre corrugated plates
	Blind windows
	Painted plates
	Currently façade rehabilitation



East



West



LEGEND	
	Facade without finished of fibre corrugated plates
	Currently façade rehabilitation
	Deteriorated concrete construction elements