

# INDEX

---

## 1- Introduction

## 2- Aim of the project

## 3- Preliminary investigation

### 3.1 Scope and methodology.

- Survey metric descriptive.
- Survey fotografic.
- Study materials and construction.
- Study pathologies of materials.
- Study of material damage.
- Functional study
- 

### 3.2 Information of the building.

#### 3.2.1 Location of the building

#### 3.2.2 Building environment

#### 3.2.3 Description

- Basement
- Ground floor
- First, second, third and fourth floor

### 3.3 Descriptive report according current situation building.

#### 3.3.1 Building systems and material used.

- Foundation
- Enclosure
- Pillars
- Partitions
- Wrought
- Deck

- Finishes
- Window frames

### 3.4 Building communication.

## 4- Detailed investigation

### 2.1 Introduction

### 2.2 Documentation and location of the pathologies.

- Enclosure
- Window frames
- Deck
- Installations
- Interior coatings
- Expansion joint
- Oxidized elements

## 5- study building. Floorplans

### 5.1 Lifting metric-descriptive

#### 5.1.1 Site plan

#### 5.1.2 Floor plants

- Basement
- Ground floor
- First floor
- Second floor
- Third floor
- Fourth floor
- Deck

#### 5.1.3 Elevations

- North
- South
- East

- West

#### 5.1.4 Sections

- Section A-A´
- Section B-B´
- Section C-C´

#### 5.1.5 2.1.5 structure plans

- Basement
- Ground floor
- First floor
- Second floor
- Third floor
- Fourth floor

-

### 6- Study materials and constructive

#### 6.1 floor plants

- Basement
- Ground floor
- First floor
- Second floor
- Third floor
- Fourth floor

#### 6.2 Elevations

- North
- South
- East
- West

### 7- Field observations and evaluation of the pathologies.

#### 7.1 Pathological tabs

- Description (situation, potos... )
- Possible causes.
- Evaluation of rehabilitation alternatives (interventions)
- Propose solution.
- Details.

#### 7.2 Overview of pathologies

- 1- Leaks on deck
- 2- Windows frames
- 3- Humidity in the outside wall
- 4- Downpipes
- 5- Breakage façade
- 6- Fall of tiles
- 7- Deteriorated external stairs
- 8- Uncoated ledge
- 9- Dirt expansion strip
- 10- Oxidation and external moisture
- 11- Incorrect water evacuation
- 12- Ramp in poor condition
- 13- Oxidation profiles
- 14- Cracks in interior stairs
- 15- Pavement crack
- 16- Simple brick breakage
- 17- Crack in brick facing
- 18- Installation
- 19- Overheating trough outside doorframes

### 8- Photographic memory

#### 9- Final report.

- 9.1 Observations
- 9.2 Conclusion
- 9.3 Bibliography