

Technical sketching according to the ISO drawing standards

Beatriz Defez García
Guillermo Peris Fajarnés
Carlos Miguel Rubió Sanvalero
Ignacio Tortajada Montañana



Beatriz Defez García
Guillermo Peris Fajarnés
Carlos Miguel Rubió Sanvalero
Ignacio Tortajada Montañana

Technical sketching according to the ISO drawing standards

EDITORIAL
UNIVERSITAT POLITÈCNICA DE VALÈNCIA

The publication of this book has been approved by the Department of Graphics Engineering of the Universitat Politècnica de València (Spain)

Academic book collection

To cite this publication please use the following reference: DEFEZ GARCÍA, B., [et al] (2015)*Technical sketching according to the ISO drawing standards*. Valencia: Universitat Politècnica de València

First edition, 2015

© Beatriz Defez García
Guillermo Peris Fajarnés
Carlos Miguel Rubió Sanvalero
Ignacio Tortajada Montañana

© of this edition: Editorial Universitat Politècnica de València

Distribution: Telf.: 963 877 012 / www.lalibreria.upv.es / Ref.: 4049_03_01_01

Printed in Creator Silk



ISBN: 978-84-9048-144-8

Print on demand

Any unauthorized copying, distribution, marketing, editing, and in general any other exploitation, for whatever reason, of this piece of work or any part thereof, is strictly prohibited without the authors' expressed and written permission.

Printed in Spain

TABLE OF CONTENTS

1	INTRODUCTION TO STANDARDIZATION	23
1.1	THE INTERNATIONAL STANDARDS ORGANIZATION	23
1.2	STANDARDIZATION, ACCREDITATION AND CERTIFICATION	23
2	BASIC CONVENTIONS	25
2.1	PAPER FORMATS	25
2.2	PAPER FORMAT ELEMENTS	26
2.3	TITLE BLOCK	27
2.4	LETTERING	28
2.5	SCALE	29
2.6	TYPES OF LINES	30
3	SKETCHING	33
3.1	SKETCHING PROCESS	33
3.2	FREEHAND DRAWING TECHNIQUES	34
4	CONVENTIONAL VIEWS	35
4.1	FIRST AND THIRD ANGLE PROJECTIONS	35
4.2	CHOICE OF VIEWS	37
4.3	CENTRELINES, SYMMETRY PLANES AND SYMMETRY AXES	38
4.4	SIMPLIFICATIONS FOR SURFACE INTERSECTIONS	40
4.5	SIMPLIFICATIONS FOR SURFACE TANGENCIES	41

5	NON CONVENTIONAL VIEWS.....	43
5.1	OFFSET VIEWS.....	43
5.2	PARTIAL VIEWS.....	44
5.2.1	PARTIAL DETAIL VIEWS.....	44
5.3	AUXILIARY VIEWS.....	45
5.4	BROKEN VIEWS.....	46
5.5	LOCAL VIEWS.....	47
5.6	SYMMETRICAL VIEWS.....	48
5.7	ROTATED VIEWS.....	50
6	CUTS.....	51
6.1	CUT ELEMENTS.....	52
6.2	HATCH.....	53
6.2.1	FEATURES AND COMPONENTS WITHOUT HATCH.....	57
6.3	TYPES OF CUTS.....	59
6.3.1	SYMMETRY CUT.....	59
6.3.2	HALF CUT.....	60
6.3.3	CUT BY PLANES PARALLEL TO THE PROJECTION PLANES.....	61
6.3.4	CUT BY PLANES PARALLEL TO THE PROJECTION PLANES GROUPED TOGETHER.....	62
6.3.5	AUXILIARY CUT.....	64
6.3.6	CUT BY TWO CONCURRENT PLANES.....	64
6.3.7	CUT BY SUCCESIVE PLANES GROUPED TOGETHER.....	65
6.3.8	PARTIAL CUT.....	66
6.3.9	DETAIL PARTIAL CUT.....	67

7 SECTIONS.....	69
7.1 REMOVED SECTIONS.....	69
7.1.1 REMOVED SECTIONS ON AXIS	69
7.1.2 REMOVED OFFSET SECTIONS.....	70
7.1.3 SUCCESSIVE REMOVED SECTIONS.....	71
7.2 REVOLVED SECTIONS	71
8 DIMENSIONING	73
8.1 ELEMENTS OF A DIMENSION	73
8.1.1 DIMENSION LINE	74
8.1.2 DIMENSION TEXT.....	75
8.1.3 PROJECTION LINES.....	77
8.1.4 DIMENSION ENDS	79
8.1.5 LEADERS	80
8.2 STRATEGIES FOR DIMENSIONING	81
8.3 GENERAL PRINCIPLES OF DIMENSIONING	82
8.4 TYPES OF LINES FOR DIMENSIONS.....	83
8.5 DIMENSIONING METHODS	83
8.5.1 METHOD A	83
8.5.2 METHOD B	84
8.6 ARRANGEMENT OF DIMENSIONS	85
8.6.1 SERIAL (CHAINED).....	85
8.6.2 PARALLEL (BASELINE).....	85
8.6.3 SUCCESSION	86
8.6.4 COORDINATED.....	86
8.7 SIMMETRICAL FEATURES	86
8.7.1 LOST DIMENSIONS	87

8.8	DIAMETER	89
8.8.1	DIAMETER DIMENSION PLUS SYMBOL	90
8.9	RADIUS	91
8.10	CHORD.....	94
8.11	ANGLE.....	94
8.12	ARC LENGTH.....	94
8.13	CHAMFER.....	94
8.14	BLIND HOLE	96
8.15	COUNTERSINK.....	96
8.16	SQUARE DIMENSION AND TWO DIAGONAL SYMBOL	97
8.17	SPHERICAL SURFACES	99
8.17.1	SPHERE DIAMETER.....	99
8.17.2	SPHERE RADIUS.....	99
8.18	REPETITIVE FEATURES.....	100
8.18.1	CARTESIAN PATTERN.....	100
8.18.2	POLAR PATTERN	102
8.19	CONICAL SURFACES: TAPER AND INCLINATION	104
8.20	SECONDARY FEATURES	106
9	THREADS.....	107
9.1	CLASSIFICATION	107
9.1.1	GENDER.....	107
9.1.2	PROFILE.....	107
9.1.3	DIRECTION	108
9.1.4	NUMBER OF ENTRANCES	108
9.2	MAIN ELEMENTS	108

9.3	REPRESENTATION OF THREADS	110
9.3.1	LATERAL AND END PROJECTIONS.....	110
9.3.2	COMPULSORY AND NON-COMPULSORY FEATURES	110
9.3.3	TYPES OF LINES	111
9.4	DIMENSIONING THREADS	113
9.4.1	COMPULSORY DIMENSIONS.....	113
9.4.2	NON-COMPULSORY DIMENSIONS.....	114
9.5	CONVENTIONAL AND SIMPLIFIED REPRESENTATIONS	114
9.5.1	SCREW.....	114
9.5.2	NUT ON A THROUGH HOLE	115
9.5.3	NUT ON A BLIND HOLE.....	115
9.5.4	DIMENSIONING THE END VIEW.....	116
9.6	HIDDEN THREADS	116
9.6.1	CUTS AND ASSEMBLY SCREW-NUT.....	117
9.7	SPECIAL THREADS.....	117
9.7.1	SHORT DESIGNATION	118
9.8	REPRESENTATION AND DIMENSIONING OF SMALL OR REPETITIVE THREADS	120
10	ASSEMBLIES.....	123
10.1	DRAWING TYPES.....	123
10.1.1	EXPLODED DRAWING	123
10.1.2	ASSEMBLY DRAWING	125
10.1.3	MULTIPLE DETAIL DRAWING.....	126
10.1.4	DETAIL DRAWING	127
10.2	ITEM NUMBER.....	128
10.3	ITEMS LIST	129
10.4	ASSEMBLIES TITLE BLOCK	129
10.5	REPRESENTATION OF STANDARD PARTS.....	129

11 ROUGHNESS	131
11.1 ROUGHNESS SYMBOL.....	131
11.2 ROUGHNESS VALUES AND ISO N-GRADES	133
11.3 PROCESS PRINT	133
11.4 INDICATION OF ROUGHNESS	134
11.4.1 EXAMPLE OF ROUGHNESS INDICATION	134
11.5 ALTERNATIVE INDICATIONS OF ROUGHNESS	135
12 SIZE TOLERANCE.....	139
12.1 DEFINITIONS.....	139
12.2 TOLERANCE NOTATION	140
12.2.1 NUMERIC NOTATION.....	140
12.2.2 ISO NOTATION	142
12.3 TOLERANCE ZONE.....	142
12.3.1 CONFIGURATIONS OF THE TOLERANCE ZONE.....	142
12.3.2 ISO TOLERANCE ZONE CHART.....	144
12.3.3 TOLERANCE EXAMPLE I	145
12.3.4 TOLERANCE EXAMPLE II	146
12.4 FITS.....	147
12.4.1 TYPES OF FITS	147
12.4.2 FIT EXAMPLE I.....	149
12.4.3 FIT EXAMPLE II.....	150
12.5 HOLE AND SHAFT BASIS SYSTEMS	151
12.5.1 HOLE BASIS SYSTEM.....	151
12.5.2 SHAFT BASIS SYSTEM.....	152

13 GEOMETRIC TOLERANCE.....	153
13.1 GEOMETRIC TOLERANCE FRAME.....	153
13.2 ALTERNATIVES TO INDICATE THE FEATURE UNDER CONTROL AND THE DATUM.....	154
13.3 LIST OF GEOMETRIC TOLERANCES AND EXAMPLES.....	157
13.3.1 FORM.....	157
13.3.2 ORIENTATION.....	159
13.3.3 PROFILE.....	161
13.3.4 RUN-OUT.....	161
13.3.5 LOCATION.....	163
13.4 OTHER CONDITIONS.....	165
13.4.1 EXAMPLE OF MMR.....	166
13.4.2 EXAMPLE OF LMR.....	167
13.4.3 EXAMPLE OF MATERIAL REQUIREMENT APPLIED TO A DATUM.....	168
14 BIBLIOGRAPHY	171

LIST OF FIGURES

Figure 1. Size correlation of A-series formats.....	26
Figure 2. Paper format basic elements	27
Figure 3. Arrangement of the identification area of the title block	27
Figure 4. Parameters of standard letters	29
Figure 5. Appearance of drawing lines	31
Figure 6. Techniques for freehand representation of inclined lines and circumferences	34
Figure 7. First angle (above) and third angle (below) orthographic representations. Three-dimensional sketch	36
Figure 8. First angle (left) and third angle (right) orthographic representations. Technical drawing.....	37
Figure 9. Symbol of the first angle (left) and third angle (right) orthographic system	37
Figure 10. Cartesian centrelines, symmetry planes and symmetry axes representation.....	39
Figure 11. Polar centrelines representation.....	39
Figure 12. Intersection between flat and curved surfaces. Realistic side view (above) and simplified side view (below)	40
Figure 13. Intersection between curved surfaces. Realistic side view (above) and simplified side view (below).....	40
Figure 14. Tangency between straight and curved surfaces. Representation using open hooks (above) and using a phantom line (below).....	41
Figure 15. Tangency between curved surfaces. Representation using closing hooks	41
Figure 16. Offset view.....	43
Figure 17. Conventional representation of an object (above), partial view using an uneven closing line (below-left) and using a zigzagged closing line (below-right)....	44

Figure 18. Partial detail view	45
Figure 19. Representation of an oblique surface: Realistic representation (left) and representation using an offset and partial auxiliary view (right)	46
Figure 20. Broken view of a solid cylinder employing narrow solid zigzagged lines. The real length of the part is 100 mm	46
Figure 21. Broken view of a solid cylinder (above) and a tube (below) employing uneven breaking lines. The real length of the parts is 100 mm	47
Figure 22. Conventional representation (above) and representation using a local view (below)	48
Figure 23. Conventional representation of an object (left), simple application of the symmetry simplification (centre) and double application of the symmetry simplification (right)	49
Figure 24. Symmetry simplification extending all lines beyond the symmetry planes: simple application (left) and double application (right)	49
Figure 25. Representation of an object with an odd number of features of cylindrical symmetry: realistic representation (left), mental rotation of the non-parallel ribs (centre), and rotated view (right).....	50
Figure 26. Cutting process of a perforated box	51
Figure 27. Representation of a perforated box using views plus hidden lines (left) and using a cut which produces a cross-section (right)	52
Figure 28. Incorrect combination of cross-section and hidden lines (left) and correct cross-section without hidden lines (right)	53
Figure 29. Hatching at 45° to main outlines.....	54
Figure 30. Incorrect non-uniform hatch (left) and correct uniform hatch (right).....	54
Figure 31. Hatch variations for the parts of an assembly represented by a cross-section. Example of assembly made of three different parts	55
Figure 32. Hatch of slim parts	56
Figure 33. Hatch of large parts	56
Figure 34. Longitudinal cross-section (left) and transversal cross-section (right) of a part with two solid ribs.....	57
Figure 35. Longitudinal cross-section of a shaft-disk assembly: incorrect hatch of the solid shaft (left), and correct representation of the solid shaft (right).....	58

Figure 36. Transversal cross-section of a shaft-disk assembly.....	58
Figure 37. Symmetry cut with cutting plane identification (left) and without cutting plane identification (right)	59
Figure 38. Symmetry cut of an axisymmetrical part: realistic cross-section (left) and simplified cross-section (right).....	60
Figure 39. Half cut: incorrect representation of hidden surfaces and cutting edge (left), correct representation without cutting plane identification (centre) and correct representation using identification (right)	61
Figure 40. Part represented by parallel cutting planes A-A and B-B.....	62
Figure 41. Cut by parallel cutting planes grouped together: incorrect representation of the cutting edge (left), and correct omission of the cutting edge (right)	63
Figure 42. Cut by parallel cutting planes grouped together. Representation labeling all the different cutting planes	63
Figure 43. Auxiliary cut (hatch angle 45° to the main outlines of the cross-section). The projection of the cut integrates a small portion of a view at the right-bottom corner	64
Figure 44. Cut by two concurrent planes	65
Figure 45. Cut by successive planes grouped together	66
Figure 46. Incorrect partial cut (left) and correct partial cut options (centre, right and far right)	67
Figure 47. Detail partial cut	68
Figure 48. Removed section on axis.....	70
Figure 49. Removed offset section	70
Figure 50. Successive removed sections on axis.....	71
Figure 51. Successive removed offset sections	71
Figure 52. Representation of a solid pedestal using a revolved section.....	72
Figure 53. Representation of a hollow wheel using a revolved section plus hidden lines	72
Figure 54. Geometrical representation of a rectangular prism (left) and full representation including dimensions (right)	73
Figure 55. Elements of a dimension.....	73

Para seguir leyendo haga click aquí