

South elavation




North elavation




Apartments


After demolition and removing of old building components we placed new windows, doors, other building components and made new brick works.




Offices



External wall



Basement



Also we upgraded building facade to make building look better and because vetilated facade has many benefits. The main reasons why we chosen ventilated facade system are:

- High Energy Efficiency
- Natural Ventilation
- Better thermal insulation during winter time
- Protection of the building overheat during summer time
- High Sound insulation